Please note the following changes made to the user's manual that is included with your mainboard.

1. The chassis intrusion detection with mnemonics during power loss feature was removed. Therefore, the Chassis Intrusion Detection (J3) connector as shown on page15 will not be available in your motherboard.

2. The One 9-Pin COM2 connector ribbon cable mention on Section 1-3 is an optional item which does not come with the mainboard package (see page 5 figure 1-3).