

ADDENDUM

The following section pertains to pages **4, 6, 9,** and **55-63** of the **Thunder 2500 S1867 User Manual Rev. 1.01** and **previous versions**.



About the SCSI bus

SCSI bus speed is limited to 33MHz, regardless of whether an LSI 53C1010-66 or LSI 53C1010-33 chip is installed.

The following section pertains to pages **4, 6, 9, 14,** and **26** of the **Thunder 2500 S1867 User Manual Rev. 1.00** and **previous versions**.

About the 66MHz PCI bus

66MHz speed on the PCI bus will not be enabled if one or more of the following occurs:

-  If there is/are a 33MHz PCI card(s) installed into the 66MHz PCI slot(s) (slots 4 and 5, if you count the PCI slot nearest to the AGP slot, as slot 1)
-  If the CPU(s) have a limit of 100MHz FSB

The following section pertains to pages **4, 7,** and **24** of the **Thunder 2500 S1867 User Manual Rev. 1.01** and **previous versions**.

About UltraDMA compatibility

UDMA66/100 IDE devices are compatible, but UDMA/66/100 transfer speeds are not possible